

NONTOXIC FINISH FOR TOYS

ONE PINT MINERAL OIL

½ CUP SHAVED BEESWAX (firmly packed)

Heat oil to a *maximum* of 150 degrees Fahrenheit*. Add the wax shavings to the hot oil. Stir until melted.

- Always monitor the thermometer

Apply with a brush and wipe off excess with a cloth.